



GRAND STAIRCASE

Historic photo of the Grand Staircase




Early 1900s

Up till 2013, the Grand Staircase was covered in concrete and trees



Before 2013



Now

Project stakeholders go by the principle of "minimum intervention, maximum retention"

Grand Staircase After - Restored to its full glory



To retain authenticity, the stairs was restored with limestone, the original material used to construct the mosque

Original sampan moorings preserved at the second base of the Grand Staircase

1900

2017

1970s



View of the Grand Staircase in the 1970s

2014-2015 Recovery in progress



JWN & KWP collaborated to ensure the Grand Staircase was retained

In 2014, the concrete embankment was stripped away to reveal the Grand Staircase



Artist impression with flooding of the Grand Staircase